## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	2	"5404104".pn.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 07:42
S2	2	"6160403".pn.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 07:53
S3	2	"6936158".pn.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 08:00
S4	2	"20030169058"	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 08:10
S5	0	"2064124" and UK	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 08:21
S6	8	"2064124"	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 08:21
S7	369	324/700.ccls.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 08:27
S8	1	324/700.ccls. and metal near5 probe same two part	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 09:18

S9	34	324/700.ccls. and metal near5 probe	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 09:19
S10	15	hermetic and (metal near5 probe) and (reference near5 probe)	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 09:31
S11	2	measuring apparatus and connector and (AC current) and (AC voltage) and current source and (computer or processor)	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 09:47
S12	5	connector and (current near5 meter) and (AC voltage near5 meter) and current source and (storage)	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 09:55
S13	7	connector and (current near5 measur \$5) and (AC voltage near5 measur\$5) and current source and (storage)	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 09:59
S14	0	connector and (current near5 measur \$5) and (AC voltage near5 measur\$5) and current source and (storage) and housing	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 10:10
S15	6	connector and (current near5 measur \$5) and (AC voltage near5 measur\$5) and current source and (storage) and case	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 10:10
S16	5	"2003006148"	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 10:31
S17	2	"20030006148"	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 10:32

S18	0	WO-0000689did.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 13:46
S19	1	WO-0000689-\$.did.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 13:46
S20	0	WO-200000689-\$.did.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 13:47
S21	0	WO-200142764-\$.did.	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/29 13:47
S22	369	corrosion same pipe and soil and measure	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/30 10:09
S23	2	corrosion same pipe and soil and measure same diagnos\$5	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/30 10:09
S24	254	corrosion same pipe and soil and measure not "2008" not "2007" not "2006"	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/30 10:10
S25	118	corrosion near5 pipe and soil and measure not "2008" not "2007" not "2006"	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/30 10:13
S26	22	corrosion near5 pipe and soil and measure near4 current not "2008" not "2007" not "2006"	US-PGPUB; USPAT; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2008/04/30 11:11

S27	27	corrosion near5 pipe	US-PGPUB;	ADJ	OFF	2008/04/30
		and soil and	USPAT; FPRS;			11:23
		measurement same	EPO; JPO;			
		voltage and	DERWENT;			
		measurement same	IBM_TDB			
		current not "2008" not				
		"2007" not "2006"				

4/30/2008 2:16:53 PM

C:\ Documents and Settings\ Bbaldridge\ My Documents\ EAST\ Workspaces\ 10591226.wsp